## Oil Field Environmental Incident Summary

Responsible Party: Wolding Trucking

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: SKUNK CREEK 1-8-17-16H

Field Name: SOUTH FORK Well File #: 26122

Date Incident:8/3/2015Time Incident:19:00Facility ID Number:County:DUNNTwp:148Rng:93Sec:8Qtr:

Location Description:

Submitted By: Ross Chaffin Received By:

Contact Person: Ross Chaffin

9121 33rd Lane NW New Town, ND 58763

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units
Oil 10 Barrels 6 Barrels 6 barrels

**Brine** 

Other

**Description of Other Released Contaminant:** 

none

Inspected: Written Report Received: 9/15/2015 Clean Up Concluded: 8/20/2015

Risk Evaluation:

low

Areal Extent:

## Potential Environmental Impacts:

low

## Action Taken or Planned:

oil was immediately sucked up and a clay dike was built around spill area

Wastes Disposal Location: Solids will be hauled to a disposal to be determined latter, oil that was

immediately sucked up was transferred to an onsite tank.

Agencies Involved:

## **Updates**

Date: 8/4/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release, due to a tank leak, remained on location according to the report. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.